

HAZARDOUS SUBSTANCES RISK ASSESSMENT

Designer Contracts Ltd

Unit 8, Church View, Coney Green, Chesterfield, S45 9HA

CPL - Mapei Latexplan Trade Comp A	Date of Assessment : 08/08/2024	Reference : CPL - Mapei Latexplan Trade Comp A
Risk Assessor : Laura Cross	Risk Assessor :	
Other People Involved in Making This Assessment : Antony Maidens		



R or H Descriptors:	S or P Descriptors:
H317 May cause an allergic skin reaction H318 Causes serious eye damage	P261 Avoid breathing dust/fume/gas/mist/vapours/spray P280 Wear protective gloves/protective clothing/eye protection/face protection P310 Immediately call a POISON CENTER or doctor/physician P362 Take off contaminated clothing and wash before reuse P305+351+338 IF IN EYES; Rinse cautiously with water for several minutes. Remove contact lenses if present and easy to do - continue rinsing P333+313 If skin irritation or a rash occurs Get medical advice/attention P501 Dispose of contents/container to ...xxxxx
Additional Information P501 Dispose of contents/ container in accordance with national regulations.	
Workspace Exposure Limit (WEL) No WEL stated on Safety Data Sheet	

Primary route(s) of entry : Absorption, Ingestion, Inhalation	
This is a Group C Substance.	The quantity used per batch or work period is: Medium (1-1000kg or 1-1000L)
The Substance is a Solid of High dustiness	
Containment is the control measure appropriate to control the health risks from the use of this substance. Health Surveillance is not required.	

Existing Control Measures
1. . Description of first aid measures In case of skin contact: Immediately take off all contaminated clothing. Areas of the body that have - or are only even suspected of having - come into contact with the product must be rinsed immediately with plenty of running water and possibly with soap.

2. OBTAIN IMMEDIATE MEDICAL ATTENTION. Wash thoroughly the body (shower or bath). Remove contaminated clothing immediately and dispose of safely.
3. In case of eyes contact: After contact with the eyes, rinse with water with the eyelids open for a sufficient length of time, then consult an ophthalmologist immediately. Protect uninjured ey
4. In case of Ingestion: Do not induce vomiting, get medical attention showing the SDS and the hazard label. In case of Inhalation: Remove casualty to fresh air and keep warm and at rest.
5. Suitable extinguishing media: Water. Carbon dioxide (CO2). Extinguishing media which must not be used for safety reasons: None in particular.
6. Special hazards arising from the substance or mixture Do not inhale explosion and combustion gases.
7. Personal precautions, protective equipment and emergency procedures Wear personal protection equipment.Remove persons to safety
8. Environmental precautions Do not allow to enter into soil/subsoil. Do not allow to enter into surface water or drains
9. Methods and material for containment and cleaning up Take up mechanically and dispose of according to local/state/federal regulations Scoop into containers and seal for disposal. Retain contaminated washing water and dispose it
10. Precautions for safe handling Avoid contact with skin and eyes, inhalation of vapours and mists. Don't use empty container before they have been cleaned. Before making transfer operations, assure that there aren't any incompatible material residuals in the containers.
11. Contaminated clothing should be changed before entering eating areas. Do not eat or drink while working.
12. Conditions for safe storage, including any incompatibilities Keep away from food, drink and feed
13. Eye protection: Use close fitting safety goggles, don't use eye lens.
14. Protection for skin: Use clothing that provides comprehensive protection to the skin, e.g. cotton, rubber, PVC or viton.
15. Protection for hands: Suitable materials for safety gloves; EN ISO 374:
16. Respiratory protection: Personal Protective Equipment should comply with relevant CE standards (as EN ISO 374 for gloves and EN ISO 166 for goggles), correctly maintained and stored.
17. ALWAYS USE IN A WELL VENTILATED AREA Respiratory protection must be used where exposure levels exceed workplace exposure limits. Refer to appropriate EN standards, like EN 136, 140, 143, 149, 14387 for information on selection and use of appropriate respiratory protection equipment.
18. A dust mask (P2) should be worn if above exposure limits (EN 149)
19. Dispose of surplus and nonrecyclable products via a licensed waste disposal contractor. Do not dispose of waste into sewers
20. Hazardous waste: Yes
21. Disposal considerations: Do not allow to enter drains or watercourses. Dispose of product according to all federal, state and local applicable regulations. If this product is mixed with other wastes, the original waste product code may no longer apply and the appropriate code should be assigned.
22. Dispose of containers contaminated by the product in accordance with local or national legal provisions. For further information, contact your local waste authority All empty packaging to be returned to region and disposed of in Drum B

Documents Associated with this Risk Assessment : Latexplan Trade Comp A.pdf(SDS)

Review Date : 16/08/2025