

## HAZARDOUS SUBSTANCES RISK ASSESSMENT

### Designer Contracts Ltd

Unit 8, Church View, Coney Green, Chesterfield, S45 9HA

<b>CPL Tilemaster Prime plus</b>	<b>Date of Assessment :</b> 06/02/2025	<b>Reference :</b> CPL - Tilemaster Prime Plus
<b>Risk Assessor :</b> Laura Cross	<b>Risk Assessor :</b>	
<b>Other People Involved in Making This Assessment :</b> Antony Maidens		

<b>R or H Descriptors:</b>	<b>S or P Descriptors:</b>
<b>Additional Information</b>	
<b>Workspace Exposure Limit (WEL)</b> No WEL stated on Safety Data Sheet	

<b>Primary route(s) of entry :</b> Absorption, Ingestion, Inhalation	
<b>This is a Group Substance.</b>	<b>The quantity used per batch or work period is:</b> Medium (1-1000kg or 1-1000L)
<b>The Substance is a Liquid of Low volatility</b>	
<b>is the control measure appropriate to control the health risks from the use of this substance. Health Surveillance is not required.</b>	

<b>Existing Control Measures</b>
1. Use in well ventilated areas.
2. First Aid Measures: Eye contact: Bathe the eye with running water for 15 minutes. Skin contact: Wash off immediately with plenty of soap and water. Ingestion: Rinse mouth thoroughly.
3. Firefighting measures: Use extinguishing media appropriate to the surrounding fire conditions. Special hazards arising from the substance or mixture: In combustion emits toxic fumes.
4. Advice for firefighters: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes.
5. Do not allow product to enter drains.
6. Methods and material for containment and cleaning up: Absorb with inert, absorbent material. Transfer to suitable, labelled containers for disposal.
7. Store in original container. Store in a cool, well ventilated area. Keep container tightly closed. The floor must be impermeable to prevent the escape of liquid.
8. Wear suitable PPE and gloves
9. Dispose of as Non Hazardous Waste. Transfer to suitable, labelled containers for disposal. Contact a licensed waste disposal company. EWC - 08 04 10 All empty packaging to be returned to region and disposed of in Drum A

**Documents Associated with this Risk Assessment : MSDS-TilemasterPrimePlus.pdf(Safety Data Sheet)**

**Review Date : 06/02/2026**