HAZARDOUS SUBSTANCES RISK ASSESSMENT

Designer Contracts Ltd

Unit 8, Church View, Coney Green, Chesterfield, S45 9HA

CPL Xtrafloor HT Adhesive	Date of Assessment : 27/06/2024	Reference : CPL - Xtrafloor HT Adhesive
Risk Assessor : Laura Cross	Risk Assessor :	
Other People Involved in Making This Assessment : Antony Maidens		

R or H Descriptors:	S or P Descriptors:	
Additional Information		
Workspace Exposure Limit (WEL)		
No WEL stated on SDS		

	Primary route(s) of entry: Absorption, Ingestion, Inhalation		
	This is a Group Substance.	The quantity used per batch or work period is: Medium (1-1000kg or 1-1000L)	
The Substance is a Liquid of Low volatility			

is the control measure appropriate to control the health risks from the use of this substance. Health Surveillance is not required.

Existing Control Measures

- 1. Always use in a well ventilated area.
- 2. First Aid: In case of skin contact: Wash with plenty of water and soap. In case of eyes contact: Wash Immediately with water.
- 3. First Aid Cont.. In case of Ingestion: Do not under any circumstances induce vomiting. In case of inhalation: Remove casualty to fresh air and keep warm and at rest.
- 4. Extinguishing media Suitable extinguishing media: Water, Carbon dioxide CO2
- 5. Accidental release measures: Limit leakages with earth or sand. Do not allow to enter into soil/subsoil. Do not allow to enter into surface water or drains. Retain contaminated washing water and dispose it.
- 6. Methods and material for containment and cleaning up Suitable material for taking up: absorbing material, organic, sand Wash with plenty of water. Retain contaminated washing water and dispose it.
- 7. Avoid contact with skin and eyes, inhalation of vapours and mists. Do not eat or drink while working
- 8. Exposure controls: Eye protection, not needed for normal use, Operate according to good working practise. protection for skin: no special precaution must be adopted for normal use. protection for hands, safty gloves EN ISO 374
- 9. Respiratory protection; PPE should comply with relevant CE Standards correctly maintained and stored.
- 10. Always wash hands after handling product.



- 11. Do not dispose of waste into sewers Do not contaminate ponds, waterways or ditches with chemical or used container. send to authorised waste disposal service.
- 12. Waste Disposal : Disposal of hardened product (EC waste code): 08 04 10 Disposal of not hardened product (EC waste code): 08 04 16 All empty packaging to be returned to region and disposed of in Drum A

Documents Associated with this Risk Assessment: IVC New HT Adhesive MSDS 010219.pdf(SDS) MSDSXtrafloor HT Adhesive_EN.pdf(Safety Data Sheet)

Review Date: 29/06/2025

